

Confirm Job No :- 2046387

Works –Highway Drainage

On site - October 2022

Location :- Chalk Hill, Cockernhoe (Adj. Offley Footpath 007)

FLOODED BEFORE



FLOODED BEFORE



ISSUE :- Carriageway permanently holding water (above) , Verge & Ditch line overrun

SOLUTION :- Reinstate Ditch Berm, Install Kerbed & lined Grips incl. Verge markers.

Install 2 No. soakaways with overflows

Silted Ditch regraded & Carriageway sided out throughout.

Confirm Job No :- 2046387

Works –Highway Drainage

On site - October 2022

Location :- Chalk Hill, Cockernhoe (Adj. Offley Footpath 007)

BEFORE



AFTER



Confirm Job No :- 2046387

Works –Highway Drainage

On site - October 2022

Location :- Chalk Hill, Cockernhoe (Adj. Offley Footpath 007)

BEFORE



SOAKAWAY INSTALLED



Confirm Job No :- 2046387

Works –Highway Drainage

On site - October 2022

Location :- Chalk Hill, Cockernhoe (Adj. Offley Footpath 007)

BEFORE



SOAKAWAY INSTALLED & DITCH REGRADE



Confirm Job No :- 2046387

Works –Highway Drainage

On site - October 2022

Location :- Chalk Hill, Cockernhoe (Adj. Offley Footpath 007)

FLOODED BEFORE



KERBED & CONC. LINED GRIPS INSTALLED (incl. Verge markers)



Confirm Job No :- 2046387

Works –Highway Drainage

On site - October 2022

Location :- Chalk Hill, Cockernhoe (Adj. Offley Footpath 007)

FLOODED BEFORE



SOAKAWAY, DITCH REGRADE & GRIPS

